



THERMA-HYGROMETER (WITH PROBE)

Temperature Measure

This therma-hygrometer indicates and records the maximum and minimum readings while also displaying the humidity and temperature simultaneously. Using internal sensors, the therma-hygrometer monitors both humidity and temperature across a range of 0 to 49.9°C and 20 to 99 percent relative humidity. The temperature range is extended to -49.9 to 69.9°C by using the external temperature sensor. The therma-hygrometer features a temperature alert alarm that will sound when the external remote temperature probe indicates the temperature is 0°C or below. This feature is ideal for frost/freeze alert in horticulture and similar.

Features:

- Internal sensors & external temperature probe.
- Dual LCD for temperature & humidity.
- Ice-point (0 °C) alert.

Technical Specifications :

Model Number	NL 7062 X / 004
Range - in	0 - 49.9 °C
Range - out	-49.9 - 68.9 °C
Range - humidity	20 - 99 %RH
Resolution	0.1 °C/°F & 1 %RH
Accuracy	±1 °C & ±5 %RH
Battery	1.5 volt AAA
Battery Life	10000 hours
Display	Dual Custom LCD
Dimension	20 x 54 x 97 mm
Approx. Weight	70g